Oil Field Environmental Incident Summary

Incident: 20141219115920

Date/Time of Notice: 12/19/2014 11:59

Responsible Party: Frac Shack Well Operator: XTO ENERGY INC. Well Name: ERNEST FEDERAL 31X-19G Field Name: HAYSTACK BUTTE Well File #: 28396 Date Incident: 12/19/2014 Time Incident: 04:00 Facility ID Number: DUNN **Twp:** 148 **Rna:** 97 **Sec:** 19 **Qtr:** County: Location Description: Submitted By: Jeremy Waldschmidt Received By: Contact Person: Adam Grasty 13021 HWY 85 North Arnegard, ND 58835 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Pump Leak Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Units Spilled Recovered Units Followup Units Oil **Brine** Other 2 Barrels **Barrels Description of Other Released Contaminant:** Diesel fuel. Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: none. Areal Extent:

Friday, February 10, 2017 Page 1 of 2

Potential Environmental Impacts:

none.

Action Taken or Planned:

Ensure that a minimum of 2 operators (valves) are present and valves in correct position. Frac Shack took all responsibility of the spill and clean up, along with the removal of affected material.

Wastes Disposal Location: Nuverra Environmental Solutions.

Agencies Involved:

Updates

Date: 12/19/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pump leak during fracking activities, remained on location according to the report. NDIC retains oversight.